

## **ÖZET**

### **KOROZYONA UĞRAYAN YAPILARDA HASAR TESBİTT VE EKONOMİK ONARIM-GÜÇLENDİRME YÖNTEMLERİİN BELİRLENMESİ**

*ALACA Zeynel Niğde Üniversitesi Fen Bilimleri Enstitüsü İnşaat Anabilim Dalı*

*Danışman: Prof. Dr. Zarife HANMEHMETOVA*

*Ağustos 1998, 80 Sayfa*

Ankara'da bulunan Deniz Kuvvetleri Komutanlığı Karargah Binası'nın bodrum katında Bulunan betonarme kolonlarda görülen korozyonun sebepleri, yaptığı tahribat incelenmiştir ve alınması gerekliliği görülen önlemler ve takviye yöntemleri sunulmuştur.

Anahtar Sözcükler: Korozyon, Hasar, Onarım

## **SUMMARY**

### **DETERMINATION OF DAMAGE FOR THE BUILDINGS EXPOSED TO CORROSION AND DETERMINATION OF METHODS FOR THE ECONOMICAL REPAIR AND REINFORCING**

*ALACA Zeynel University of Niğde The Graduate School of Natural and Applied Sciences Department of Civil Engineering*

*Supervisor : Prof. Dr. Zarife HANMEHMETOVA*

*August 1998, 80 Pages*

The reasons of the corrosion and its damage in the reinforced concrete columns have been examined in the basement floor of Naval Forced Headquarter building in Ankara. The precautions which should be taken and the methods of reinforcing / repair have been determined.

Key Words : Corrosion, Damage, Repair.